

F. Resolución	Nº Homologación	Fabricante	Tipo	Marcas
09/08/2021	CF13*19*1393 REV. 01	OPEL ESPAÑA, S.L.U.	INSIGNIA_ST_55R	OPEL
09/08/2021	CF13*19*1393	OPEL ESPAÑA, S.L.U.	INSIGNIA_ST_55R	OPEL
09/08/2021	CF13*19*1391	OPEL ESPAÑA, S.L.U.	GRANDLAND_55R	OPEL
09/08/2021	CF13*19*1392	OPEL ESPAÑA, S.L.U.	INSIGNIA_HB5_55R	OPEL
09/08/2021	CF13*18*1364	OPEL ESPAÑA, S.L.U.	CF Estriberas Grandland X	OPEL
09/08/2021	CF13*18*1365	OPEL ESPAÑA, S.L.U.	CF Estriberas Crossland X	OPEL
09/08/2021	CF01*14*4056	OPEL ESPAÑA, S.L.U.	ESTRIBOS LATERALES	OPEL
25/10/2021	CF04*12*3089	BMW IBERICA, S.A.	SISTEMA DE FRENADO DELANTERO BMW X5 (E53)	BMW
04/11/2021	CF107*20*5076*00 REV. 01	CNH INDUSTRIAL EUROPE HOLDING, S.A.	I12940	NEW HOLLAND
04/11/2021	CF107*20*5076*00	CNH INDUSTRIAL EUROPE HOLDING, S.A.	I12940	NEW HOLLAND
04/11/2021	CF107*20*5076*00 Rev 02_ERROR	SPECIAL CAB, S.R.L.	I12940	SPECIAL CAB
29/11/2021	CF01*17*4282	EMERGENCIA 2000 S.A.	Mod-E2000-MVI	EMERGENCIA 2000
29/11/2021	CF15*15*2018*00	EMERGENCIA 2000 S.A.	Mod-E2000-MSI	EMERGENCIA 2000
01/12/2021	CF01*13*4028	MOBIS PARTS EUROPE N.V. – ZWEIGNIEDERLASSUNG DEUTSCHLAND	SNSS1	MOBIS PARTS EUROPE N.V